



JON M. HUNTSMAN, JR.

Governor

GARY R. HERBERT

Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
November 7, 2005

Supervisor DRZ

Mine Name: Levin Stone 4
Operator Name: Levin Stone Company
Box 95
Ash Fork, AZ. 86320
Inspector(s): Tom Munson
Other Participants: None
Mine Status: Inactive

Permit number: S/027/086
Inspection Date: Oct. 20, 2005
Time: 2:00PM-2:30 PM

Weather: Sunny

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

The purpose of the inspection was to determine the extent of disturbance remaining at the site.

Directions to Site:

The site is near trilobite location in the House Range.

Inspection Summary:

The site was not expanded or changed since I had visited it previously.

Conclusions and Recommendations:

The operator be contacted to determine what they are planning on doing with the site. The annual fee has not been paid and the BLM notified me to say that the bond was being cancelled.

Inspector's Signature Thomas Munson

Date: November 7, 2005

TM:jb

cc: Van Falls, Levin Stone
BLM, Fillmore

Attachment: GPS & Photos

PIT AREA
↓






PARKING AREA



LEVIN STONE #4


S027/086



LEVIN STONE #4

PARENIDE

510271086



LFVIN STONE #4 5027/08E

Mine Number: S0270086
Mine Name: Levin Stone 4
Township 17 S Range 13 W Section 27, 34 SLBM

Inspection Date Oct. 20, 2005
 Map Produced by DKS

Acres Disturbed	3.08
Acres Regraded	0
Acres Seeded	0
Road Acres Disturbed	0

Total Acres Disturbed	3.08
------------------------------	-------------

Acres Released	0
Acres Excluded	0
Acres PreExisting	0
Acres Prelaw	0

Legend

All items symbolized in legend may not be appear on map

- | | |
|-----------------|---|
| County Boundary | Township or range Line |
| Access | Township or range line: location doubtful |
| Mine | Section line |
| NonMine | Section line: location doubtful |
| Other | Disturbed |
| Interstate | Regraded |
| US Route | Seeded |
| State Route | Released |
| Primary Route | Excluded |
| Secondary Route | PreExisting |
| Main Dirt Road | Prelaw |
| Unimproved Road | Bond Area |
| Interchange | SITLA Mineral Leases |
| Trail | BLM Salable Minerals |
| | Community Pit |

DOQ imagery date 1998



0 625
 Feet
 1:7,500 1 inch equals 625 feet
 Verify Scale

Dept. of Natural Resources
 Division of Oil, Gas, and Mining
 Mineral Mines Program

Different data sources and input scales
 may cause misalignment of data layers.
 This product may not meet DGM
 standards for accuracy and content.